



Gantry images

WL G=0, C=0, P=0; Field=(40, 40)mm; BB=4mm @ left=0, in=0, up=0; Gantry tilt=0, Gantry sag=0.dcm




G=0, B=0, P=0

WL G=90, C=0, P=0; Field=(40, 40)mm; BB=4mm @ left=0, in=0, up=0; Gantry tilt=0, Gantry sag=0.dcm




G=90, B=0, P=0

WL G=180, C=0, P=0; Field=(40, 40)mm; BB=4mm @ left=0, in=0, up=0; Gantry tilt=0, Gantry sag=0.dcm



G=180, B=0, P=0

WL G=270, C=0, P=0; Field=(40, 40)mm; BB=4mm @ left=0, in=0, up=0; Gantry tilt=0, Gantry sag=0.dcm



G=270, B=0, P=0