



Gantry images


wl_dir/WL G=0, C=0, P=0;
Field=(40, 40)mm; BB=4mm @
left=0, in=0, up=0; Gantry
tilt=0, Gantry sag=0.dcm



wl_dir/WL G=90, C=0, P=0;
Field=(40, 40)mm; BB=4mm @
left=0, in=0, up=0; Gantry
tilt=0, Gantry sag=0.dcm



wl_dir/WL G=180, C=0, P=0;
Field=(40, 40)mm; BB=4mm @
left=0, in=0, up=0; Gantry
tilt=0, Gantry sag=0.dcm



wl_dir/WL G=270, C=0, P=0;
Field=(40, 40)mm; BB=4mm @
left=0, in=0, up=0; Gantry
tilt=0, Gantry sag=0.dcm

