



Gantry images

wl_dir/WL G=0, C=0, P=0;
Cone=17.5mm; BB=4mm @ left=0,
in=0, up=0; Gantry tilt=0,
Gantry sag=0.dcm




G=0, B=0, P=0

wl_dir/WL G=90, C=0, P=0;
Cone=17.5mm; BB=4mm @ left=0,
in=0, up=0; Gantry tilt=0,
Gantry sag=0.dcm




G=90, B=0, P=0

wl_dir/WL G=180, C=0, P=0;
Cone=17.5mm; BB=4mm @ left=0,
in=0, up=0; Gantry tilt=0,
Gantry sag=0.dcm



G=180, B=0, P=0

wl_dir/WL G=270, C=0, P=0;
Cone=17.5mm; BB=4mm @ left=0,
in=0, up=0; Gantry tilt=0,
Gantry sag=0.dcm



G=270, B=0, P=0