

WL G=180, C=0, P=0; Field=(20,
20)mm (shifts=((0, 0, 0), (20,
-20, 60))); BB=5mm @
left=19.95, in=59.83,
up=-21.62; Gantry tilt=0,
Gantry sag=0.dcm

