

WL G=0, C=0, P=0; Field=(20,  
20)mm (shifts=((0, 0, 0), (20,  
-20, 60))); BB=5mm @  
left=18.72, in=59.48,  
up=-21.34; Gantry tilt=0,  
Gantry sag=0.dcm

