

WL G=180, C=0, P=0; Field=(20, 20)mm (shifts=((0, 0, 0), (20, -20, 60))); BB=5mm @ left=18.59, in=61.20, up=-18.73; Gantry tilt=0, Gantry sag=0.dcm

