

WL G=0, C=0, P=0; Field=(20,
20)mm (shifts=((0, 0, 0), (20,
-20, 60))); BB=5mm @
left=21.96, in=59.26,
up=-21.27; Gantry tilt=0,
Gantry sag=0.dcm

