



GBP Combo images


WL G=0, C=0, P=0; Field=(20, 20)mm; BB=5mm @ left=2, in=0, up=0; Gantry tilt=0, Gantry sag=0.dcm




WL G=0, C=0, P=90; Field=(20, 20)mm; BB=5mm @ left=2, in=0, up=0; Gantry tilt=0, Gantry sag=0.dcm




WL G=0, C=0, P=315; Field=(20, 20)mm; BB=5mm @ left=2, in=0, up=0; Gantry tilt=0, Gantry sag=0.dcm




WL G=0, C=45, P=0; Field=(20, 20)mm; BB=5mm @ left=2, in=0, up=0; Gantry tilt=0, Gantry sag=0.dcm




WL G=0, C=270, P=0; Field=(20, 20)mm; BB=5mm @ left=2, in=0, up=0; Gantry tilt=0, Gantry sag=0.dcm



WL G=90, C=0, P=0; Field=(20, 20)mm; BB=5mm @ left=2, in=0, up=0; Gantry tilt=0, Gantry sag=0.dcm



WL G=180, C=0, P=0; Field=(20, 20)mm; BB=5mm @ left=2, in=0, up=0; Gantry tilt=0, Gantry sag=0.dcm



WL G=270, C=0, P=0; Field=(20, 20)mm; BB=5mm @ left=2, in=0, up=0; Gantry tilt=0, Gantry sag=0.dcm

